



- FLAG NOTES ○
- Axis lines not given.
 - Submittals are not available.
 - Reflected Ceiling layout not available.
 - ① Pipe bottom level is very low.
 - ② Pipe clashes with reflected ceiling level. (Architect to lower ceiling height to accommodate piping)

FIRST FLOOR PARTIAL PLAN

THIS DRAWING IS A PRESENTATION OF A PROPOSED LAYOUT. IT IS THE CONTRACTOR'S RESPONSIBILITY TO VERIFY AND REVIEW PRIOR TO FINAL SUBMISSION. CAD/SULTANTS IS NOT RESPONSIBLE FOR DISCREPANCY IN THE FIELD. ANY CORRECTIONS TO THE DRAWING IS REQUIRED BY THE CONTRACTOR TO ADVISE CAD/SULTANTS BEFORE FINAL SUBMISSION & BEFORE FABRICATION OR INSTALLATION.

NO.	DATE	DESCRIPTION
7	12/20/18	UPDATED AS PER COMMENTS.
6	09/04/18	UPDATED AS PER COMMENTS.
5	02/26/18	REVISED AS PER LATEST STRUCTURAL DRAWING.
4	02/14/18	REVISED AS PER COMMENTS.
3	02/10/18	REVISED AS PER COMMENTS.
2	01/10/18	UPDATED AS PER ADDENDUM #1.
1	11/06/17	COORDINATION UPDATED.

PLUMBING CONTRACTOR:
Titan Realty & Construction
 One Plaza Road
 Greenvale, New York 11548
 T. 516-348-1200 x 143
 F. 516-348-1201
 E. Nawad@titannewyork.com

DRAFTING COMPANY:
CADD/SULTANTS
 Certified CAD Specialist
 All Types of Drafting
MARC HOFFMAN
 167 Allen Road
 Rockville Centre NY, 11570
 Contact: 646.641.2519
 Email: Cadd@sultan@yahoo.com

ADDRESS:
NEW MIXED USE DEVELOPMENT
 575 4th AVENUE
 BROOKLYN, 11215

PROJECT INFORMATION:
FIRST FLOOR (PART-B)
COMBINED SERVICES LAYOUT
 Scale: 1/4"=1'-0" 08/05/17 Drawing Number
 PAGE SIZE 36x48 P-101B